



## Follow-up Service Inspection Report E2373201231013113307

INSPECTION DETAILS			
Date:	2023-10-13	File Number.:	E237320
Responsible Office:	Taipei	Volume:	1
Inspection Center:	820	CCN:	ZPFW2
Product Type:	Wiring Harness - Form N	UL Rep Name:	Mike Yeh
Deliverable Type:	Recognized	UL Rep ID:	26485
Party Site Number:	600794	Subscriber Factory No.:	825557-001
Manufacturer Name:	ELECTRON DRIVE INDEX CO LTD	Factory Rep Name:	Ms. Joyce Kao, 高聖晴
Manufacturer Address:	No.13 Xinjiang N Rd Xizhi District New Taipei	Factory Rep Phone:	02-26482525, 288
		Factory Rep Email:	sales@edicom.com.tw
Applicant:	ELECTRON DRIVE INDEX CO LTD (600794) No.13 Xinjiang N Rd, Xizhi District New Taipei 221031 TW		
Nature of visit:	Regular Inspection	Sample Status:	Samples not required
UL Marks Used?	Yes	UL Marks Removed?	No
Variation Notice Issued?	No	Specific Environmental Conditions Required?	No

PRODUCT DOCUMENTS/PRODUCTION READY VISIT			
Model	Product	Section	Multiple Listed
E35G104040202	Wiring Harness	1	No

UL-OWNED EQUIPMENT CALIBRATION
No UL Owned IMTE used during inspection.

COMMENTS	
Additional Comments	
Comments After Submission:	

In addition to the requirements specified in the applicable UL Services agreement and Follow-Up Service Procedure, UL further defines responsibilities, duties and requirements for both manufacturers and UL representatives in the document titled "UL Mark Surveillance Requirements" that can be located at [www.ul.com/fus](http://www.ul.com/fus), and in accordance with the applicable terms and conditions of the document at [www.ul.com/responsibilities](http://www.ul.com/responsibilities). Manufacturers without Internet access may obtain the current versions of these documents from their local UL customer service representative or UL field representative. The Field Engineer is completing the inspections per Internal Procedure UL Mark Surveillance Program Policy Manual -ULID-004573.